EGS Configuration (Change que	est				ac	ge 1 of	/ . Pa	age(s)
1. Originator	2. Log Date: 3. CCR						1 -		6. Off:	
Byron V. Peters	11/27/98	8	98-12	228		4	077		SED	F.WE
8. Title of Change: Install Al	MASS on journéy ar	nd t1acg	01 for optical	l browse						
9. Originator Signature)	1 10	Data		11. Clas	- 140	T		40 No. 4	<u> </u>	10/44/00
9. Originator Signature) 10. Date:			98	11. Class 12. Type:				13. Need Date: 12/11/98		
14. Office Manager Signature 15. Date:				16. Date CCB 17. C			17. Cat	ategory of 18. Priority:		
			/ / 1		ision Needed:		Change):	Routi	-
Thereby 1/27			27/78	<u> </u>			Categor			
19. Documentation/Drawing 929 TDM 002; 920-TDV-002		20. Schedule Impact: 21. Cl(s) Affected: ACM, STMGT						STMGT		
000	None									
22. Release Affected: Drop 4PX			. Date due	24.	Impl. Da	ite: ,		Effectivity	of	26. Est.
Drop 4PX			Customer:N/A 12/1			190		Change:		Cost Hone
27. Source Reference: NCR (attach) Action item GSFC CCR Tecn Ref. Other:										
28. Description of Change	: (use additional S	Sheets it	necessary)						
Development needs to have an optical browse capability in the Mini-DAAC and VATC environments in order to verify the browse functionality works with an optical library.										
i unctionality works with all of	nical library.									
-										
29. Proposed Solution: (us	se additional shee	ts if nec	essary)							
Modify the disk partitions on	journey and t1acg0	1 to acco	ommodate A	MASS requ	irements	s (ama	sscache,	filesysdb a	and files	sysdb
journal). Install AMASS on journel, controller (each) on journey,	urney and t1acg01.	Install a	n existing So	CSI switch to	connec	ct the th	ree exis	ting optical	drives	to a single
controller (each) on journey,	aven and tracgor.									
20 Alternate Solution: (us	a additional about	a if mans								
30. Alternate Solution: (use additional sheets if necessary) None										
31. Consequences if Change							انطمممانا	lteria impalae		at the
Continued use of disk to star DAACs.	id in for the optical t	devices i	may result ir	i problems v	vnen tne	ориса	і саравіі	ity is impiei	menteu	at tn ·
00 0 01 4# 4		/D 1								
32. Does Change Affect An Maintenance Training				additional : ☐Safety		ice [Suppor	t □Test		
Baseline (XRP)		, por uno.					_cappo.			
33. Organization(s) Affe				Contracts]Chief]FOS]M&C
	□QO □ □Sys. Dev. [2	Rel De		Procuremen Sys Verf Ac		RTSC Other	L	Sci. Data E	ng ∐	Security
34. Site(s) Affected: □E							JSIDC	□ѕмс [TAK [T.IFI
	OC Other	٠٠٠٠					10.00		_,	
35. Board Comments:								36. Work Assigned To		
							ļ	CM,	RTS	<u> </u>
							1			
37. Release Authorized (For CM Use Only): Yes No 38. CM Verified/Signature and Date										
39. EDF/REL2 CCB Chair (Sign/Date):, 40. Disposition: App Ap/C 41. ESDIS ERB Concurrence:										
39. EDF/HEL2 CCB (Thair (sign/Date):	40. [: XIApp oved ∐W	∐Ap/C /ithdrau		41. ES[ЛS ERB C	oncurr	ence:
1 Mille	10 141 <i>198</i>		☐Fwd/EC			'				
42 ECS CCB Chair (Sign/D	Pate):	43. Di	sposition:			\dashv	44. CCI	R Closed E	ate:	
	·		isApproved							

CM01 August 27, 1998

ECS/EDF/REL2 CCB



